

DATE OF LAST INSPECTION 12.06.2008)
HARYANA URBAN DEVELOPMENT AUTHORITY PANCHKULA
(REPORT OF SUBSEQUENTI INSPECTION
SECTOR: 3 I & II Rewari
URBAN ESTATE:-REWARI

1	NAME & Designation of the inspection officer	Sh. Roshan Lal Estate Officer	
2	Date of present inspection	26.03.2009	
3	Date of last inspection(s)	12.06.2008	
4	are there any sites in respect of which possession has not been offered? If so give details	-----	
5	Is there any change in plot details since last inspection? If yes, give detail	NO	
6	No of plots/sites in respect of which litigation is going on. Full details may be given by means of Annexures.	-----	
7	Whether registered RWR exists if yes, names of president and General Secretary	YES Exist, Sh. Sunil Rao Adv. President & Dr. R. K. Yadav G/S	
8	Whether advance notice given and RWA representative present at the time of inspection	Yes Present	
9	Action taken to improve deficiencies noted during last inspection.		
	Sr. No	Infrastructure/activities	Steps taken to improve
	1	Roads	Pot Hole Appears Filled Up
	2	Water supply	8 complaints for Leakages Removed
	3	Sewerage	10 Complaints of Over Flowing Removed
	4	Storm water	Nil Nil
	5	Parks	Nil Nil
	6	Street Lights	Nil Nil
	7	Sineages	Nil Nil
	8	Cleanliness	Nil Nil
	9	Removal of encroachment	Nil Nil
	10	Unplanned area	Nil Nil
	11	Entries of the sector	Nil Nil
	12	Maintenance of Community Building	Nil Nil
	13	Reduction in litigation	Nil Nil
10	Whether Assessment form filled up by RWA is enclosed or Not?	Yes, Enclosed	
11	Total time taken for inspection of the	1 ½ HR	

	Sector	
12	Names of the officials who accompanied the EO during inspection	
	(A) JE (Civil)	Sh. Naresh Kumar
	(B) JE (Electrical)	Sh. Harvinder Singh
	(C) JE (Horti)	Sh Surender Sharma
	(D) JE (Estate Officer)	Sh. Om Parkash Manjhu
13	Overall Assessment : Whether physical condition and maintenance of Sector helps in Improving Image Of HUDA?	Yes physical condition and maintenance of Sector helps in Improving Image Of HUDA.

Signature of the Inspecting Officer.

1	Whether the representative present during last inspection.	
2	Overall mark out of 10 marks in the last inspection.	
A	JE (Civil) for water supply, sewerage & street lighting	4
B	JE (Electrical) for Street light	5
C	JE (Horti) for Parks	7
D	JE (Estate Officer) for cleanliness, maintenance of open spaces, drainage, prevention & removal of encroachments	5
E	Steps taken to improve deficiencies noted during the last inspection.	

Signature of the Inspecting Officer
 Signature of the Representative of RWA

TO BE FILLED UP BY INSPECTING OFFICER


Whether the Responding officer agree	There was problem of water supply. Parks are
Signature of the Responding officer	
Signature of the Inspecting Officer	and situation improved a lot

Name & Signature of the Inspecting Officer

ASSESSMENT FORM TO BE FILLED UP BY RESIDENT WELFARE ASSOCIATION


DATE OF INSPECTION = 26-03-2009

1	Name of RWA	JUDA Resident Welfare Association Sec-3 Rewari
2	Registration number Act under which registered & date of registration	2109 dtf 28-03-1997
3	Name & Address, Mobile No. e-mail address of the President and General secretary	Sunil Rao HNO 444, sec. 3 Part I 9896010123
4	Name(S) of the representative present during last inspection.	Sunil Rao
4	Assessment out of 10 marks in respect of:	
A	JE (Civil) for water supply, sewerage & storm water	4
B	JE (Electrical) for Street light	5
C	JE (Hort.) for Parks	7
D	JE (Estate Office) for cleanliness maintenance of open spaces, sineages, prevention & removal of encroachments.	5
E	Steps taken to improve deficiencies noted during the last inspection	


Signature of President / Gen. Secy./
Authorised Representative of RWA.

TO BE FILLED UP BY INSPECTING OFFICER

Whether the Inspecting officer agrees with the above Assessment done by RWA? If not, then what is his Assessment and reasons therefore.	There is no problem of water supply. Parks are well maintained. Sineages are in good conditions. Inspecting officer himself took pain for knowing the grievances and redressal of their grievances and situation improved a lot
---	---


Name & Signature of the
Inspecting officer